

CLASSIFIED MESSAGE

Approved For Release 2002/09/05 : CIA-RDP89B00569R000800180031-4
DATE 0008Z 08 APR 64

SECRET

ROUTING	
1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

TO : DIRECTOR

25X1A

FROM: [REDACTED]

ACTION:

OPS 1-8

INFO :

TOR 0444Z 08 APR 64

25X1A

25X1A

ROUTINE

IN 72216

TO

[REDACTED]

INFO

[REDACTED]

CITE

[REDACTED]

25X1A

A. S154A

25X1A

B. B/119 D7/5,354

[REDACTED]

C. HTA-3B/D -19/2°/78 DEGREES

D. 2.09 2.02/2.01 2.01

E. 8402/232-28-7-3 (9L) 327-27-7-3 (9R)

F. (1) GOOD

(2) GOOD

(3) GOOD

(4) GOOD

(5) GOOD

(6) GOOD

(7) OPERATING

G. REMARKS: TAKE RECEIVED AT 07/0140Z APR IN COVERED, METAL BOXES. ONE SIDE SEALED; OTHER UNSEALED. PROCESSED TRACKER RECEIVED FROM S144A IN GOOD CONDITION. SLIGHT CREASE FIRST FEW FRAMES 9L DUE TO HEAT SEAL SPLICE. DEVELOPER STREAK IN FRAME 0017L. MILD PRESSURE

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

25X1A

[REDACTED] (IN 72216)

S E C R E T

PAGE TWO

MARKS FIRST 1000 FRAMES 9R. FRAMES DID NOT MATCH AT END OF TAKE.
9R HAD 1721; 9L HAD 1732. NO OVERRUN WAS NOTED ON EITHER SIDE.
MANUFACTURER SPLICES NOTED ON FRAMES 0008R AND L. CONFIGURATION
OPERATED SATISFACTORILY.

END OF MESSAGE

S E C R E T